



Photograph #1: 11/29/12 Area 1, view facing southwest.



Photograph #2: 11/29/12 Area 1, view facing northeast.



Photograph #5: 11/29/12 Area 1, view facing northwest.



Photograph #6: 11/29/12 Area 1, view facing northeast.



Photograph #7: 5/4/11 Area 2, view facing east towards Area 1.



Photograph #8: 5/4/11 Area 2, Bldg. 624, view facing west.



Photograph #9: 5/4/11 Areas 2 and 4, view facing northeast.



Photograph #10: 5/4/11 Area 2, Bldg. 624, view facing northeast.



Photograph #11: 5/4/11 Area 2, view facing north.



Photograph #12: 5/4/11 Area 2, Bldg. 624, view facing east.



Photograph #13: 5/4/11 Area 3, view looking north.



Photograph #14: 11/29/12, Area 3
Stake in foreground is position of sampling location AI3-105 adjacent to pressure-treated deck.



Photograph #15: 5/4/11 Area 3, view looking south.



Photograph #16: 5/4/11 Area 3 by Bldg's 614 and 615, view facing northeast.



Photograph #17: 5/4/11 Area 3, view facing south



Photograph #18: 5/4/11 Area 3, view facing north.



Photograph #19: 5/4/11 Area 3, view facing southeast.



Photograph #20: Area 3, south end, view facing south.



Photograph #21: 5/4/11 West side of Area 3, view facing south.



Photograph #22: 5/4/11 Areas 2 and 4, view facing south



Photograph #23: 5/4/11 Area 4, Bldg. 625, view facing east.



Photograph #24: 11/29/12 Area 4, Evidence of fill at hole dug at adjacent sampling locations B-05 and SS-5. Coal, concrete, and a shell.



Photograph #25: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location B-06. Coal and asphalt.



Photograph #26: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location SS-12. Crushed stone up to 2-inch diameter, coal and asphalt.



Photograph #27: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location AI4-102. Coal, asphalt-coated rocks, rusty nail, and glass.



Photograph #28: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location AI4-106. Crushed stone up to 2 inches in diameter, coal, and asphalt.



Photograph #29: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location AI4-108. Bricks and coal.



Photograph #30: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location AI4-108. Wire and bricks.



Photograph #31: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location AI4-111. Coal and brick.



Photograph #32: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location AI4-111. Coal and coal ash in hole.



Photograph #33: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location AI4-112. Coal. Glass was observed in the hole during backfilling.



Photograph #34: 11/29/12 Area 4, Evidence of fill at hole dug at sampling location AI4-113. Coal and brick.



Photograph #35: 5/4/11 Area 5, Bldg. 615, view from Area 3 facing west.



Photograph #36: 5/4/11 Area 5, Bldg. 615 on right, view facing west.



Photograph #37: 5/4/11 Area 5, Bldg. 614, view from Area 3 facing southwest.



Photograph #38: 5/4/11 Area 5, Bldg. 615 on right, view from Area 3 facing west.



Photograph #39: 5/4/11 Area 5, between Bldg's 614 and 615, view facing south.



Photograph #40: 5/4/11 Area 5, Bldg. 614 on left, view facing west.



Photograph #41: 5/4/11 Area 5, Bldg 615. on left, view facing north.



Photograph #42: 5/4/11 Area 5, Bldg. 615 on left, view facing northwest.



Photograph #43: 5/4/11 Area 5, Bldg. 614 on right, view facing south.



Photograph #44: 11/28/12 Area 5. View facing northwest towards south end of Bldg. 615; Approximate locations of former soil boring SB-08 and former sample locations SS-41, SS-42, S-43, and SS-44, and former excavation area.



Photograph #45: 11/28/12 Area 5. View facing northwest towards south end of Bldg. 615, buried utility corridor, and former excavation area.



Photograph #46: 11/28/12 Area 5. View facing north-northwest towards south end of Bldg. 615, buried utility corridor, and former excavation area.



Photograph #47: 11/28/12 Area 5. View facing northwest towards south end of Bldg. 615, former soil boring AI5-105, and former excavation area.



Photograph #48: 11/28/12 Area 5. View facing north-northwest towards south end of Bldg. 615.



Photograph #49: 11/28/12 Area 5. View facing northwest between Bldg. 615 and Bldg. 614, former soil boring AI5-109, and former excavation area.



Photograph #50: 11/28/12 Area 5. View facing northwest towards south end of Bldg. 615, former soil boring AI5-103, and former excavation area.



Photograph #51: 11/28/12 Area 5. Some of the roots recovered from MW-4R via the water level meter.