

**Evergreen Mill Creek Point Mitigation Bank
Photos**



The Evergreen Mill Creek Point Mitigation Bank is in the center of the photo and appears as yellow/brown Phragmites with a curving shoreline associated with Mill Creek. Note that MCP is not inundated, while the MRI3 Mitigation Bank to the left of the white LNG tanks is inundated by the high tide.



Facing east from edge of ball fields across the site composed mainly of Phragmites.



Facing southeast from edge of ball fields across site composed mainly of Phragmites.



Interface of ball fields and mitigation site, facing north.



Mill Creek at the northern edge of the site.


Figures



 Proposed Restoration Area

 Evergreen Mill Creek Point Mitigation Bank Property Boundary

Aerial: (c) 2010 Microsoft Corporation and its data suppliers



Proposed Restoration Area
 Evergreen Mill Creek Point Mitigation Bank, Secaucus, Hudson County, NJ

Figure
 1



 parcels
 Mill Ridge Rd Site
 Aerial: (c) 2010 Microsoft Corporation
 and its data suppliers

