

**REPORT OF CHANNEL CONDITIONS  
400 FEET WIDE OR GREATER  
(ER 1130-2-306)**

**PAGE** 1 **OF** 1

**DATE** 16 September 2003

**TO:** Commander 90 (OAN), First Coast Guard District  
408 Atlantic Avenue  
Boston, MA 02110

**FROM:** U.S. Army Corps of Engineers  
26 Federal Plaza, ATTN: CENAN-OP-ST  
New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:

SANDY HOOK CHANNEL, NJ

**MINIMUM DEPTHS IN  
CHANNEL ENTERING FROM SEAWARD**

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nmiles)	DEPTH (feet)				
Reach A – East Section	13-22 Aug 2003	800	3.4	35	38.0	36.4	37.4	30.8
Reach B – Bay Side	13-22 Aug 2003	800	3.7	35	22.3	38.7	36.9	33.9

REMARKS:

1. Some small shoals occur along the edges of the channel, including a 6000-8000 ft. long shoal in the Right Outside section of Reach A.