

Appendix A

Photograph Log

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 1: Typical Silo Access Hatch (4/12/18).



Photograph 2: Water treatment system (4/17/18).

APPENDIX A SITE PHOTOGRAPHS



Photograph 3: Dewatering Silo 2 (4/23/18).



Photograph 4: Water treatment system discharge (4/25/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 5: Point where discharge meets Cazenovia Creek (4/25/18).



Photograph 6: Dewatering elevator shaft inside Silo 2 (5/1/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 7: Interior of Silo 5 after dewatering (5/15/18).




Photograph 8: Soil and debris located in Silo 1 stairwell (5/15/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 9: Debris inside Silo 1 (5/17/18).



Photograph 10: Hydraulic system and associated piping removal from Silo 2 (6/7/18).

APPENDIX A SITE PHOTOGRAPHS




Photograph 11: Debris removal from Silo 1 (6/25/18).



Photograph 12: Asbestos removal inside Silo 5 (7/10/18).

APPENDIX A SITE PHOTOGRAPHS



Photograph 13: Silo 2 pressure washed and ready for demo (7/12/18).



Photograph 14: Non friable asbestos inside roll off container (7/17/18).

APPENDIX A SITE PHOTOGRAPHS



Photograph 15: Elevator doors removed at Silo 4 (7/24/18).



Photograph 16: Concrete core sample collected from Silo 5 roof (7/26/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 17: Excavation to remove asbestos containing transite piping from Silo 1 (8/6/18).



Photograph 18: Roof coating removal from Silo 2 (8/9/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 19: Hammering concrete launch pad at Silo 2 (8/22/18).



Photograph 20: Excavation at Silo 1 (8/29/18).

APPENDIX A SITE PHOTOGRAPHS



Photograph 21: Excavation of side wall at Silo 2 and covered soil pile (9/4/18).



Photograph 22: Excavation and dewatering at previously demolished Silo 6 (9/20/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 23: Demolition of side walls at Silo 4 (10/10/18).



Photograph 24: Demolition of support beams and elevator door platform at Silo 4 (10/10/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 25: Excavation around personnel room and stairwell at Silo 4 (10/11/18).



Photograph 26: Removing elevator piston at Silo 6 (11/6/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 27: Demolition at Silo 6 (11/7/18).



Photograph 28: Walls removed as demolition continues at Silo 6 (11/8/18).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 29: Backfill with soil and crushed concrete at Silo 1 (11/12/18).



Photograph 30: Backfill with soil and crushed concrete at Silo 6 (11/13/18).

APPENDIX A SITE PHOTOGRAPHS



Photograph 31: Water treatment system setup (04/15/19).



Photograph 32: Water treatment system sample collection (04/17/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 33: Water treatment system discharge structure (04/19/19).



Photograph 34: Concrete crushing to reduce concrete size (04/23/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 35: Demolition at Silo 5 (04/25/19).



Photograph 36: Demolition continues at Silo 5 (04/30/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 37: Demolition at Silo 3 (05/02/19).



Photograph 38: Demolition of walls at Silo 5 (05/06/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 39: Demolition of Silo 2 Roof (05/14/19).



Photograph 40: Silo 2 Elevator Frame Removal (05/20/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 41: Pumping hydraulic oil from elevator piston assembly (05/21/19).



Photograph 42: Crushing concrete into smaller sized pieces for use as backfill (05/28/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 43: Asbestos abatement at Silo 2 (05/29/19).



Photograph 44: Backfill Silo 5 with native soil (06/03/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 45: Backfill compaction testing at Silo 5 (06/04/19).



Photograph 46: Backfill Silo 2 with imported fill (06/12/19).

APPENDIX A SITE PHOTOGRAPHS



Photograph 47: Compaction of silo (06/26/19).



Photograph 48: Backfill compaction testing (06/27/19).

APPENDIX A SITE PHOTOGRAPHS



Photograph 49: Backfill compaction of former silo area (07/01/19).



Photograph 50: Survey for final grading (07/02/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 51: Overview of former silo area (07/03/19).



Photograph 52: Placement of native topsoil (07/09/19).

APPENDIX A SITE PHOTOGRAPHS



Photograph 53: Native topsoil placement (07/10/19).



Photograph 54: Hydroseeding site (07/16/19).

**APPENDIX A
SITE PHOTOGRAPHS**



Photograph 55: Grass growing across site (07/22/19).