

REPORT OF CHANNEL CONDITIONS
400 FEET WIDE OR GREATER
(ER 1130-2-306)

PAGE 1 OF 1

DATE Mar 5, 2002

TO: Commander, First Coast Guard District
 408 Atlantic Ave.
 Boston, MA 02110-2290

FROM: U.S. Army Corps of Engineers
 26 Federal Plaza, ATTN: CENAN-OP-ST
 New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:
 Newark Bay, Hackensack & Passaic Rivers, NJ

**MINIMUM DEPTHS IN EACH ¼ WIDTH OF
 CHANNEL ENTERING FROM SEAWARD**

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	LEFT INSIDE QUARTER <i>(feet)</i>	RIGHT INSIDE QUARTER <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>				
Port Elizabeth Pierhead Channel	21 Feb 02	950-580	1.26	40	38.0	38.6	38.8	39.3

REMARKS *(Continue on reverse)*

1. All depths are in Mean Low Water.
2. A narrow shoal crosses the entire channel at the entrance.
3. Shoals expand across almost the entire left half of the channel at the beginning and at the end of the reach