

**REPORT OF CHANNEL CONDITIONS
400 FEET WIDE OR GREATER
(ER 1130-2-306)**

PAGE 1 OF 1

DATE March 5, 2002

TO: THE RECORD

FROM: U.S. Army Corps of Engineers
26 Federal Plaza
New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:

GRAVESEND BAY ANCHORAGE, NEW YORK HARBOR,
NY

**MINIMUM DEPTHS IN EACH ¼ WIDTH OF
CHANNEL ENTERING FROM SEAWARD**

SECTION OR REACH	MAP FILE NO. SURVEY DATE	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	LEFT INSIDE QUARTER <i>(feet)</i>	RIGHT INSIDE QUARTER <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(nmiles)</i>	DEPTH <i>(feet)</i>				
Gravesend Bay Anchorage	Map 46 p1 of 1 6,7, &12 Feb. 2002	2,400	1.4	47	49.7	47.4	46.9	45.1

REMARKS:

All depths are in Mean Low Water (MLW)

Shoal Description- at Northeast corner of channel (right outside quarter), there is a 200 ft. wide x 1100 ft. long shoal with a minimum depth of 45.1 feet.