

**REPORT OF CHANNEL CONDITIONS
400 FEET WIDE OR GREATER
(ER 1130-2-306)**

PAGE 1 OF 1

DATE 19 October 2001

TO: The record

FROM: U.S. Army Corps of Engineers
26 Federal Plaza, ATTN: CENAN-OP-ST
New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:
JAMAICA BAY ENTRANCE CHANNEL, NEW YORK

**MINIMUM DEPTHS IN EACH ¼ WIDTH OF
CHANNEL ENTERING FROM SEAWARD**

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	LEFT INSIDE QUARTER <i>(feet)</i>	RIGHT INSIDE QUARTER <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>				
ENTRANCE CHANNEL	9/3/01	1000	1.33	20	5.9	15.8	19.9	21.2

REMARKS *(Continue on reverse)*

Shoal starting at 800' south of Green Can #5 and the shoal occur in the entire Entrance Channel with maximum width of 1/2 of the channel width.

