

**REPORT OF CHANNEL CONDITIONS  
400 FEET WIDE OR GREATER  
(ER 1130-2-306)**

**PAGE** 1 **OF** 1

**DATE** January 10, 2003

**TO:** The Record

**FROM:** U.S. Army Corps of Engineers  
26 Federal Plaza, ATTN: CENAN-OP-ST  
New York, NY 10278-0090

**RIVER/HARBOR NAME AND STATE:**  
N.Y. & N.J. CHANNELS, Ward Point Secondary Channel

**MINIMUM DEPTHS IN  
CHANNEL ENTERING FROM SEAWARD**

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nmiles)	DEPTH (feet)				
Reach T: Ward Point Secondary Channel	December 9, 2002	400	0.97	30	21.6	21.0	20.9	20.6

**REMARKS:**

- All depths in MLW
- Shoaling is abundant in each quarter throughout the middle region of channel.
- 35 – 40 Percent of channel is shoaled approximately 6 – 10 feet above authorized depth.