

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-306)**

PAGE 1 **OF** 1

DATE May 27, 2003

TO: The Record

FROM:

U.S. Army Corps of Engineers
26 Federal Plaza, ATTN: CENAN-OP-ST
New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:
EAST ROCKAWAY INLET, NEW YORK

**MINIMUM DEPTHS IN
CHANNEL ENTERING FROM
SEAWARD**

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nmiles)	DEPTH (feet)			
East Rockaway Inlet, NY	Map 176 1 thru 2 March 3, April 15, 21 2003	250	0.7	12	14.1	13.9	10.6

REMARKS:

- All depths in MLW
- Channel length is in nautical miles.
- Whole channel depth is well under project depth with a minor shoal in the Right quarter at Red Nun #4 Buoy with minimal depth of 10.6 ft.