

US Army Corps of Engineers New York District

Cumulative 5-year Sedimentation Due to Resuspension
Caused by the HDP and Other Dredging






Figure 5-4
2,3,7,8 TCDD in the sediments of Newark Bay under current conditions: Thiessen polygons, cumulative assessment





Figure 5-5

Total PCBs in the sediments of Newark Bay under current conditions: Thiessen polygons, cumulative assessment





Figure 5-6

DDTs in the sediments of Newark Bay under current conditions: Thiessen polygons, cumulative assessment





Figure 5-7
Benzo(a)pyrene in the sediments of Newark Bay under current conditions: Thiessen polygons, cumulative assessment






Figure 5-8

Mercury in the sediments of Newark Bay under current conditions: Thiessen polygons, cumulative assessment





Figure 5-9
Chromium in the sediments of Newark Bay under current conditions: Thiessen polygons, cumulative assessment