REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE

(ER 1130-2-3165)

PAGE 1 **OF** 1

DATE: January 25, 2012

(Proponent: CECW-OM)

TO: The Record

FROM: U.S. Army Corps of Engineers

OS Fordered Place ATTAN OF N

26 Federal Plaza, ATTN: CENAN-OP-ST

New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:

New York Harbor, New York - Sandy Hook Channel

MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHO WIDTH (feet)	DRIZED PR LENGTH (nmiles)	OJECT DEPTH (feet)	LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Partial Reach B: East: Bayside Reach- Survey coverage exists in the left inside and outside quarters of the channel beginning approximately 530 feet landward of GREEN LIGHT W/BELL #11 EBB and ends approximately 2,160 feet landward of the same.	Map 166 Pg 1 of 5 9-11, 13 & 17 January, 2012	800	2.3	35	+1.2	34.1	*	*
Partial Reach B: West: Bayside Reach- Survey coverage exists in the left outside quarter of the channel beginning approximately 1,160 feet landward of GREEN LIGHT W/GONG #13 EBB and ends approximately 2,670 feet landward of the same.	Map 166 Pg 1 of 5 9-11, 13 & 17 January, 2012	800	2.3	35	31.8	*	*	*

REMARKS:

- All depths in MLW.
- Channel length in nautical miles.
- * No survey coverage exists in this quarter.

NEW YORK HARBOR—SANDY HOOK CHANNEL:

- Partial Reach B: East: Severe shoaling having a minimum depth of +1.2 feet MLW exists in the entire width of the left outside quarter of the channel beginning approximately 860 feet landward of GREEN LIGHT W/BELL #11 and extends approximately 980 feet landward. Minor shoaling also exists in the left inside quarter within the same parameters of the channel.
- Partial Reach B: West: Shoaling having a minimum depth of -31.8 feet MLW exists in the left outside quarter beginning approximately 1,910 feet landward of GREEN LIGHT W/GONG #13 and extends approximately 380 feet landward having a maximum width of approximately 30 feet.