

REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-316)

PAGE 1 OF 1

DATE
 12 Jan 2012

TO:
 FOR THE RECORD

FROM:
 US ARMY ENGINEER DISTRICT, NEW YORK
 ALBANY FIELD OFFICE, 1 BOND ST TROY, NY 12180

RIVER/HARBOR NAME AND STATE
 RONDOUT HARBOR, NY

MINIMUM DEPTHS IN
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	MIDDLE HALF <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>			
RONDOUT CREEK	18/Oct/11	100	1	14	14	14	17
	18/Oct/11	100	3	12	6	5	5

REMARKS *(Continue on reverse)*

Rondout Creek has two projects depths: 14 feet for the 1.3 miles from the mouth of the Hudson River and 12 feet for 2.7 miles to the end.