

APPENDIX K
SILO EVALUATION PHOTO DOCUMENTATION



Photographs 1 & 2 - Silo #1 Water Sampling for Waste Characterization.




Photograph 3 – Looking north from Silo #1. Mobilization of Steel Tanks.



Photographs 4 & 5 – Installation of Drop Sampling Tubes



Photograph 6 – Water Sampling from Silo #5



Photograph 7- Installation of Pressure Transducer at Silo #2



Photograph 8 – Implementing Pump Test at Silo #2.



Photographs 9 & 10 – Collecting Composite Water Sample during Silo #2 Pump Test.



Photographs 11 & 12 – Securing Silo Sampling Access Holes



Photograph 13 – Cleaning Steel Tanks



Photograph 14 – Demobilization of Steel Tanks