

Waterways ShoalAreas

Miles  
0 0.5 1 1.5 2

#### LINKS TO DOCUMENTS

- 2007 NEPA Final Environmental Assessment, Newark Bay**
  - Appendix 1: Assessment of Dredging-Induced Deposition Patterns
  - Appendix 2: Evaluation of Potential Effects of HDP on Chemical Contamination
  - Appendix 3: Assessment of Suspended Sediment Plumes
  - Appendix 4: Assessment of Ship-Induced Suspended Sediment Plumes
- Ambrose Channel Obstruction**
  - 2010 Ambrose Obstruction Biological Sampling Report
  - 2012 Report: Elimination of High Spot C Obstruction - Ambrose Channel
- Dredging Feasibility Report and EIS for NY NJ Harbor Nav Study**
- Aquatic Biological Survey Multiple Years Summary Reports**
  - 2010 Application of Winter Flounder Data to Seasonal Constraints
  - 2013 Application of Winter Flounder Data to Habitat Uses
  - 2013 Application of Winter Flounder Data to Seasonal Constraints
  - 2015 Demersal Fish Assemblages of New York Bight


- 2004 Environmental Assessment on Consolidated Implementation of HDP**
  - Appendix B: Water Resources, Shoaling, Coastal Erosion
  - Appendix C: Biological Sampling
  - Appendix D: Habitat Mitigation Report
  - Appendix E: Essential Fish Habitat
  - Appendix F: Cultural Resources
- 2015 Dredge Plume Dynamics in NY/NJ Harbor**
- Harbor Air Management Plan for the NY/NJ HDP**
- 2004 Fish Communities/Potential Effect of Blasting**
- 2012 South Elizabeth Channel Silt Curtain Pilot Study**
- 2013 Essential Fish Habitat Knowledge Gained During HDP**

- Benthic Studies**
  - 1998-99 Demersal-Benthic Sampling Program
  - 2006 Harborwide Benthic Monitoring
  - 2011 Benthic Recovery Report
  - 2012 Benthic Recovery Report
  - 2017 Benthic Recovery Report: Arthur Kill

- Migratory Finfish Reports**
  - 2006 Migratory Finfish Report
  - 2011 Migratory Finfish Report
  - 2012 Migratory Finfish Report
  - 2013 Migratory Finfish Report
  - Migratory Finfish Survey Summary Report

- Acoustic Monitoring**
  - 2012 Characterization of Underwater Sounds
  - Hydraulic Cutterhead
  - Backhoe Dredge





Waterways ShoalAreas

0 0.5 1 1.5 2 Miles

#### LINKS TO DOCUMENTS

- 2007 NEPA Final Environmental Assessment, Newark Bay**
  - Appendix 1: Assessment of Dredging-Induced Deposition Patterns
  - Appendix 2: Evaluation of Potential Effects of HDP on Chemical Contamination
  - Appendix 3: Assessment of Suspended Sediment Plumes
  - Appendix 4: Assessment of Ship-Induced Suspended Sediment Plumes
- Ambrose Channel Obstruction**
  - 2010 Ambrose Obstruction Biological Sampling Report
  - 2012 Report: Elimination of High Spot C Obstruction - Ambrose Channel
- Dredging Feasibility Report and EIS for NY NJ Harbor Nav Study**
- Aquatic Biological Survey Multiple Years Summary Reports**
  - 2010 Application of Winter Flounder Data to Seasonal Constraints
  - 2013 Application of Winter Flounder Data to Habitat Uses
  - 2013 Application of Winter Flounder Data to Seasonal Constraints
  - 2015 Demersal Fish Assemblages of New York Bight

#### 2004 Environmental Assessment on Consolidated Implementation of HDP

- Appendix B: Water Resources, Shoaling, Coastal Erosion
- Appendix C: Biological Sampling
- Appendix D: Habitat Mitigation Report
- Appendix E: Essential Fish Habitat
- Appendix F: Cultural Resources

#### 2015 Dredge Plume Dynamics in NY/NJ Harbor

#### Harbor Air Management Plan for the NY/NJ HDP

#### 2004 Fish Communities/Potential Effect of Blasting

#### 2012 South Elizabeth Channel Silt Curtain Pilot Study

#### 2013 Essential Fish Habitat Knowledge Gained During HDP

- Benthic Studies**
  - 1998-99 Demersal-Benthic Sampling Program
  - 2006 Harborwide Benthic Monitoring
  - 2011 Benthic Recovery Report
  - 2012 Benthic Recovery Report
  - 2017 Benthic Recovery Report: Arthur Kill


#### Migratory Finfish Reports

- 2006 Migratory Finfish Report
- 2011 Migratory Finfish Report
- 2012 Migratory Finfish Report
- 2013 Migratory Finfish Report
- Migratory Finfish Survey Summary Report

#### Acoustic Monitoring

- 2012 Characterization of Underwater Sounds
- Hydraulic Cutterhead
- Backhoe Dredge





Waterways Shoal Areas

0 0.5 1 1.5 2 Miles

#### LINKS TO DOCUMENTS

##### 2007 NEPA Final Environmental Assessment, Newark Bay

- Appendix 1: Assessment of Dredging-Induced Deposition Patterns
- Appendix 2: Evaluation of Potential Effects of HDP on Chemical Contamination
- Appendix 3: Assessment of Suspended Sediment Plumes
- Appendix 4: Assessment of Ship-Induced Suspended Sediment Plumes

##### Ambrose Channel Obstruction

- 2010 Ambrose Obstruction Biological Sampling Report
- 2012 Report: Elimination of High Spot C Obstruction - Ambrose Channel

##### Dredging Feasibility Report and EIS for NY NJ Harbor Nav Study

##### Aquatic Biological Survey Multiple Years Summary Reports

- 2010 Application of Winter Flounder Data to Seasonal Constraints
- 2013 Application of Winter Flounder Data to Habitat Uses
- 2013 Application of Winter Flounder Data to Seasonal Constraints
- 2015 Demersal Fish Assemblages of New York Bight

##### 2004 Environmental Assessment on Consolidated Implementation of HDP

- Appendix B: Water Resources, Shoaling, Coastal Erosion
- Appendix C: Biological Sampling
- Appendix D: Habitat Mitigation Report
- Appendix E: Essential Fish Habitat
- Appendix F: Cultural Resources

##### 2015 Dredge Plume Dynamics in NY/NJ Harbor

##### Harbor Air Management Plan for the NY/NJ HDP

##### 2004 Fish Communities/Potential Effect of Blasting

##### 2012 South Elizabeth Channel Silt Curtain Pilot Study

##### 2013 Essential Fish Habitat Knowledge Gained During HDP

##### Benthic Studies

- 1998-99 Demersal-Benthic Sampling Program
- 2006 Harborwide Benthic Monitoring
- 2011 Benthic Recovery Report
- 2012 Benthic Recovery Report
- 2017 Benthic Recovery Report: Arthur Kill

##### Migratory Finfish Reports

- 2006 Migratory Finfish Report
- 2011 Migratory Finfish Report
- 2012 Migratory Finfish Report
- 2013 Migratory Finfish Report
- Migratory Finfish Survey Summary Report

##### Acoustic Monitoring

- 2012 Characterization of Underwater Sounds
- Hydraulic Cutterhead
- Backhoe Dredge

