

Appendix D:

Site Visit Photographs Taken at the Launch and Control Areas, July 14, 2015

This Page Intentionally Left Blank



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Control Area Site
Orchard Park, New York



Photograph 1- Looking east along the access road toward Old Transit Road (in background) at the BU 34/35 Nike Control Area Site. Property is vacant of structures and vegetated with isolated asphalt areas associated with former road and parking areas.



Photograph 2 – Looking west along access road toward the central portion of the BU 34/35 Nike Control Area Site.



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Control Area Site
Orchard Park, New York



Photograph 3 – Looking north on the BU 34/35 Nike Control Area Site. Property is vacant and vegetated with isolated asphalt areas associated with former access road and parking areas. Tree-line in background is off-site.



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Launch Area Site
East Aurora, New York



Photograph 1- Showing utilities (water and gas) on the BU 34/35 Nike Launch Area Site. Looking west from entrance on access road.



Photograph 2 – Showing former barracks on the BU 34/35 Nike Launch Area Site. Looking southwest from entrance on access road toward barracks.



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Launch Area Site
East Aurora, New York



Photograph 3 – Showing garage connected to former barracks building on the BU 34/35 Nike Launch Area Site. Looking west towards building from access road.



Photograph 4 – Showing entrance to former barracks on the BU 34/35 Nike Launch Area Site. Looking west toward barracks from access road,



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Launch Area Site
East Aurora, New York



Photograph 5 – Looking north along garage wall towards former barracks on the BU 34/35 Nike Launch Area Site.



Photograph 6 - Looking southeast from the former barracks/garage area toward first bend in the access road.



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Launch Area Site
East Aurora, New York



Photograph 7 – Looking southeast along access road from barracks/garage area to Silo Area on the BU 34/35 Nike Launch Area Site. Northern property boundary parallels a portion of the road on the left.



Photograph 8 – Looking southeast toward Silo Area on BU 34/35 Nike Launch Area Site.



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Launch Area Site
East Aurora, New York



Photograph 9 – Showing previously excavated Silo Area (no. 3) on the BU 34/35 Nike Launch Area Site.



Photograph 10 – Showing a top of Nike Silo structure (No. 1) on the BU 34/35 Nike Launch Area Site.



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Launch Area Site
East Aurora, New York



Photograph 11 – Showing Nike Silo structure associated with Silo 1 (same as Photograph 10) on the BU 34/35 Nike Launch Area Site. Note – black gasket.



Photograph 12 – Showing rectangular concrete slab foundation with metal cover in the vicinity of Silo no.

1



Photograph Log
Prepared by T12E
July 21, 2015

July 14, 2015, Site Visit Photographs
Nike BU 34/35 Launch Area Site
East Aurora, New York



Photograph 13 - Showing rectangular concrete slab foundation with square metal cover in the vicinity of Silo no. 1 on the BU 34/35 Nike Launch Area Site. Note – Monitoring well (MW-3) located in the upper right corner (within red circle).