

## **Appendix J**

### **Photographs**



Photo 1- Area F Excavation (2005)



Photo 2 – Area F Wet Conditions (2005)



Photo 3- Area F Excavation (2005)



Photo 4 – Area D Excavation (2005)



Photo 5 - Area F Excavation (2005)



Photo 6 – Backfill Operations (2005)





Photo 7 - Area B/C Excavation



Photo 8- Area B/C Excavation



Photo 9- Area B Excavation



Photo 10 – Area D – Drum Product Removal



Photo 11- Area D Excavation



Photo 12- Area D Excavation





Photo 13 - Area D Excavation



Photo 14- Area D Excavation



Photo 15 - Area D Excavation



Photo 16 - Area D Excavation





Photo 17 – Soil Staging (2005)



Photo 18 – Soil Staging (2005)



Photo 19- Soil Load-out Operation (2005)



Photo 20 – Soil Load-out Operation (2005)



Photo 21- Area F Excavation (2006)



Photo 22 – Area F Excavation (2006)



Photo 23- Area F Excavation



Photo 24- Area F – Soil Staging (2006)





Photo 25 - Area F Excavation – Continuing (Drum Carcasses)



Photo 26– Area F Excavation – Continuing (Drum Carcasses)



Photo 27- Area F Excavation – Slit Trench Extending South to 'Clean Fill'



Photo 28 – Area F Excavation



Photo 29 - Area F Excavation – Slit Trench North of Area F (2006)



Photo 30 – Area F Excavation – Slit Trenches North of Area F (2006)




Photo 31– Area of Interest 5 – Initial



Photo 32 – Area of Interest 5 – Continuing (Pill Bottles/Black Tar Substance)






Photo 33 – Area of Interest 5 – West Limits



Photo 34– Area of Interest 5 – East Limits



Photo 35 – Area of Interest 5 – Overall




Photo 36– Area of Interest 5 – Overall




Photo 37– Area of Interest 7 – Initial



Photo 38 – Area of Interest 7 – Completed (Nothing encountered)



Photo 39– Area of Interest 8 – Initial



Photo 40 – Area of Interest 8 – Completed (Nothing encountered)






Photo 41 – Area 'Unknown Haul Road' – Initial (White Caulk Substance Encountered)



Photo 42 – Area 'Unknown Haul Road' - Completed



Photo 43 – Soil Staging (2006)



Photo 44 – Soil Staging (2006)



Photo 45– Soil Load Out (2006)



Photo 46 – Soil Load Out (2006)





Photo 47 – Site Restored – Main Haul Road West to Area F



Photo 48 – Site Restored – Area F





Photo 49 – Site Restored – Area F



Photo 50 – Site Restored – Main Haul Road East from Area F



Photo 51 – Site Restored – Area of Interest 5 Haul Road towards East



Photo 52 – Site Restored – Soil Staging Area



Photo 53– Site Restored – Soil Staging Area



Photo 54– Site Restored – Soil Staging Area



Photo 55 – Site Restored – Office Trailer Area



Photo 56 – Site Restored – West from Crest of Main Haul Road (AOI5 on right)





Photo 57 – Site Restored – Ms. Burns Driveway



Photo 58– Site Restored – Ms. Burns Sidewalk



Photo 59 – Site Restored – Ms. Burns Driveway



Photo 60 – Site Restored – Ms. Burns Driveway